CIMFP Exhibit P-03099

GOVERNMENT OF NEWFOUNDLAND AND LABRADOR



Service NL





Page: 1 of: 1

Reference #:

0671973

Toll Free:

1-800-563-5471

INSPECTION / OFFICER'S REPORT

Inspection:

SEP 24,2016

Accident Reporting: 729-4444

SEP 24,2016

ASTALDI CANADA

Firm #:

600062

HAMILTON RIVER ROAD

WCC#:

2052257

GOOSE BAY

NL

Tel: Fax:

A0P-1C0

NIC:

Worksite:

Draft Tube Number 2

Employees:

4123

Location: Employer Co-Chair: Muskrat Falls Powerhouse, Goose Bay NL.

Employee Co-Chair:

Shem Evans

Insp. Time: 8:30AM

Neil Mulrooney

Worker Rep/Designate: N/A

REPORT:

This is a follow up inspection report on Directives issued previously by this Division. On May 30, 2016 a Stop Work Order was issued on all concrete pours on all four draft tubes and associated work until the formwork and falsework are evaluated by a P. Eng licensed to practice in this Province. This evaluation was to be in consultation with the falsework and formwork provider and an Engineering review of all associated drawings and assembly procedures and practice was to be undertaken.

A request has been received for full release of the Stop Work Order as issued on May 30, 2016. Documentation has been received and reviewed. Substantial engineering and modifications have been implemented post incident. All supporting documentation has been reviewed and accepted by LCP, aDB and SNC. Additionally, there is a full time representative from aDB in the field on a Quality Assurance basis to ensure 3rd party P.Eng verification prior to concrete placement. Site visits by the undersigned has also verified appropriate actions have been taken.

The Stop Work Order as issued in inspection report 0671924 is lifted and all work may resume.

No further Directives issued at this time.

Received By:

Date: SEP 24,2016

Position:

Time:

11:12AM

Officer's Name:

Browne, Aiden

A copy of this inspection/order report must be provided at the earliest possible opportunity to your OHS Committee, Worker Representative or Workplace Designate.